## gkkworks

 

 SCHOOL:
 IMMEDIATE NEEDS:

 MADISON ES
 PRIORITY 2

 A.
 PROVIDE BETTER LIGHTING IN CORRIDORS; PROVIDE EXTERIOR SECURITY LIGHTING.

 B.
 PROVIDE LANDSCAPING ON ALL SIDES SURROUNDING SCHOOL.

 C.
 WOOD WINDOWS AND FRAMES NEED TO BE REPAIRED OR REPLACED.

 D.
 REPLACE RUSTED CHAIN LINK FENCING WITH NEW 1" SQ, MESH WHERE NEEDED.