



SCHOOL: **NORMA-COOMBS AS** IMMEDIATE NEEDS:

- A. PROVIDE NEW FIRE ALARM DEVICES AS NEEDED THROUGHOUT THE PERMANENT CAMPUS BUILDING.
- B. MAKE EAST SIDE OF CAMPUS ADA COMPLIANT.
- C. UPGRADE THE EMS CONTROLS FOR THE HEATING AND COOLING SYSTEMS ON CAMPUS.
- D. REPLACE OLD ELECTRIC PANEL BOARDS AND LIGHTING AT THE CAFETERIA AND AUDITORIUM WITH ADEQUATE BRANCH BREAKER WITH INCREASED CAPACITY AND NEW ENERGY EFFICIENCY LIGHT FIXTURES.
- E. NEW RAMPS AND ACCESSIBLE PATHS TO THE SCHOOL BUILDINGS AT THE LOWER PLAYGROUND.
- F. REPLACE PLUMBING FIXTURES AT RESTROOM.
- G. REPLACE EXISTING CHAIR LIFT AT THE EXTERIOR HALLWAY.
- H. PROVIDE RESTROOM TO K BUILDING ON NORTH SIDE OF SCHOOL.
- I. PROVIDE ADDITIONAL SHADE STRUCTURE AT PLAYGROUND AREA.
- J. REPLACE EXTERIOR DRINKING FOUNTAINS WITH ACCESSIBLE FIXTURES.
- K. REPLACE CONTROLS FOR EXTERIOR LIGHTING THROUGHOUT CAMPUS.
- L. SEPARATE DOMESTIC/FIRE/IRRIGATION METERS.
- M. MODERNIZE THE AUDITORIUM, INCLUDING HVAC SYSTEM.



N. PROVIDE P.A. SYSTEM THROUGHOUT SCHOOL.

ESTIMATED COST OF IMMEDIATE NEEDS:

\$ 5,133,152