



SCHOOL: **SIERRA MADRE UPPER MS** IMMEDIATE NEEDS:

NOTE: THIS SCHOOL WAS NOT MODERNIZED UNDER MEASURE Y.

- A. CONSTRUCT NEW GYMNASIUM PER MIDDLE SCHOOL STANDARDS.
- B. RECONFIGURE SITE LAYOUT, UTILIZING WASTED SPACE WITH EFFICIENT PARKING DESIGN AND DROP-OFF/PICK-UP INTERIOR LOOP.
- C. UPGRADE ELECTRICAL SYSTEM THROUGHOUT.
- D. RECONSTRUCT DEFICIENT MULTI-PURPOSE ROOM, CAFETERIA AND KITCHEN. PROVIDE LUNCH SHELTER.
- E. REPLACE OLD PORTABLE BUILDINGS WITH NEW FIXED CLASSROOM STRUCTURES OR NEW PORTABLES.
- F. MODERNIZE OR RECONSTRUCT CLASSROOM, ADMINISTRATION, COMPUTER, AND LIBRARY BUILDINGS WITH CURRENT STATE-OF-THE-ART AMENITIES.
- G. MAKE ENTIRE SITE FULLY ADA COMPLIANT.
- H. IMPROVE EXTERNAL APPEARANCE OF ENTIRE CAMPUS; DEFINE MAIN ENTRANCE TO CAMPUS.
- I. RE-GRADE TO IMPROVE DRAINAGE AT AREAS PRONE TO FLOODING OR PUDDLING.
- J. REPLACE OR REPAIR WALL AC UNITS AT CLASSROOM BUILDINGS TO AVOID CONDENSATION RUN-OFF OVER MAIN PATH OF TRAVEL.
- K. PROVIDE NEW FIRE SPRINKLER SYSTEM THROUGHOUT CAMPUS.



- L. PROVIDE FIRE ALARM SYSTEM THROUGHOUT.
- M. SEPARATE DOMESTIC, FIRE AND IRRIGATION WATER METERS.
- N. REPLACE LIGHTING SYSTEMS IN BUILDINGS WITH NEW ENERGY EFFICIENT FIXTURES.
- O. REPLACE EXTERIOR LIGHTING AT MULTI-PURPOSE ROOM.

ESTIMATED COST OF IMMEDIATE NEEDS:

\$ 38,651,693