

SCHOOL: WEBSTER ES IMMEDIATE NEEDS:

- A. MODERNIZE MAIN BUILDING'S ADMIN. AREA, CAFETERIA, KITCHEN, AND AUDITORIUM TO CURRENT ELECTRICAL, MECHANICAL, LIGHTING, ACOUSTICAL, TECHNOLOGICAL, AND INTERIOR FINISH STANDARDS.
- B. REPAIR BOILERS FOR HEATING OR PROVIDE NEW SYSTEM.
- C. SEPARATE DOMESTIC, FIRE AND IRRIGATION WATER METERS.
- D. REPLACE HALLWAY AND EXTERIOR DRINKING FOUNTAINS WITH ADA COMPLIANT FIXTURES.
- E. PROVIDE VENTILATION TO ELECTRICAL CLOSET IN ROOM 111.
- F. AT THE MAIN CLASSROOM BUILDING, REPLACE OLD ELECTRIC PANEL BOARDS WITH ADEQUATE BRANCH BREAKERS WITH INCREASED CAPACITY.

ESTIMATED COST OF IMMEDIATE NEEDS:

\$ 3,934,730