

# PUSD FACILITIES PROJECT LIST

#### **Facilities Master Plan**

This project list is part of PUSD's Facilities Master Plan, which was developed through an extensive process that involved community members, parents, school and district staff.

#### Facts about PUSD School Facilities:

- Most campuses are 50 75 years old and need repair
- One local bond in 40 years to repair or upgrade schools
- Infrastructure does not meet modern educational needs

#### **Measure TT**

On November 4, Pasadena Unified School District voters will be asked whether to pass a \$350 million bond to repair and upgrade our aging and deteriorating schools.

## **Highlights of Measure TT**

- Make All School Campuses Safe, Secure and Accessible
- Provide Equal Access to High-Quality Learning and Recreational Facilities
- Enhance Student and Teacher Access to Technology
- Use Green Technology For Healthy and Efficient Buildings
- Ensure Strict Independent Oversight and Accountability

## **Fiscal Impact**

- Measure TT funds would make PUSD eligible for another \$115 million from other sources
- Costs Approximately \$44.63 Per \$100,000 of assessed – not market – property value.
- The average homeowner would pay \$9.54 per month or 31 cents per day.

# Madison Elementary School 515 Ashtabula, Pasadena CA 91004



## **Proposed Project List:**

- Restore auditorium to its historical prominence; make it accessible to community by remodeling its main entrance
- Modernize cafeteria and kitchen, and provide a lunch shelter near cafeteria.
  Provide ventilation or air conditioning to kitchen, cafeteria and multipurpose room
- Provide second trash enclosure on site in proximity to kitchen/cafeteria. Create new delivery driveway to include new trash bin area on Madison Ave.
- Separate domestic/fire/irrigation meter
- Provide shade shelters in playgrounds
- Provide K playground on south side with shade structure

- Safety issue: create driveway loop for drop-off and pick-up at north end of campus
- Provide ADA access to stage
- Provide ADA drinking fountains at exterior areas
- Replace old electric panel boards and lighting in the basement of building A with adequate branch breaker with increased capacity
- Replace plumbing fixture in kitchen and most rest rooms
- Provide ventilation to library space between ceiling and roof to prevent builtup condensation and eventual water leaks

## **Transparency & Accountability**

- Independent citizens oversight commission mandated by law to monitor allocation of bond funds
- Annual report to the public
- Public website to track progress on all projects
- Long-term Facilities Master Plan, updated quarterly and annually