



# PUSD FACILITIES PROJECT LIST

## Facilities Master Plan

This project list is part of PUSD's Facilities Master Plan, which was developed through an extensive process that involved community members, parents, school and

## Facts about PUSD School

### Facilities:

- Most campuses are 50 – 75 years old and need repair
- One local bond in 40 years to repair or upgrade schools
- Infrastructure does not meet modern educational needs

## Measure TT

On November 4, Pasadena Unified School District voters will be asked whether to pass a \$350 million bond to repair and upgrade our aging and deteriorating schools.

## Highlights of Measure TT

- Make All School Campuses Safe, Secure and Accessible
- Provide Equal Access to High-Quality Learning and Recreational Facilities
- Enhance Student and Teacher Access to Technology
- Use Green Technology For Healthy and Efficient Buildings
- Ensure Strict Independent Oversight and Accountability

## Fiscal Impact

- Measure TT funds would make PUSD eligible for another \$115 million from other sources
- Costs Approximately \$44.63 Per \$100,000 of **assessed** – not market – property value.
- The average homeowner would pay \$9.54 per month or 31 cents per day.

## Allendale School 1135 South Euclid Avenue, Pasadena, CA 91106



### Proposed Project List:

### Estimated Cost: \$ Million

#### Priority 1

- Board decision: school is not open for full service at this time

#### Priority 2

- Provide new fire alarm devices in classroom and assembly spaces
- Provide new fire sprinkler system throughout campus buildings
- Restroom ADA upgrades and repair ADA restroom features
- Additional data outlets in modular building
- Repair student lockers
- Classroom and restrooms need maintenance to include painting
- Floor replacement and change of toilet accessories
- Replace falling acoustic tile-system in several locations
- Roofs in some buildings are in poor condition and should be re-roofed
- Chain link fencing and baseball back-stops need replacement
- Provide new landscaping and irrigation to the yard north of building A
- Repair the top 1 to 3 courses of decorative brick wall at the rear yard of the classroom building

## Transparency & Accountability

- Independent citizens oversight commission mandated by law to monitor allocation of bond funds
- Annual report to the public
- Public website to track progress on all projects
- Long-term Facilities Master Plan, updated quarterly and annually

